





# VOR RWY 30

MERCED MUNI-MACREADY FIELD (MCE)

VOR/DME HYP <b>114.2</b> Chan <b>89</b>	APP CRS <b>289°</b>	Rwy Idg <b>5903</b> TDZE <b>156</b> Apt Elev <b>156</b>
-----------------------------------------------	------------------------	---------------------------------------------------------------

<p><b>⚠</b> Circling not authorized northeast of Rwy 12-30. For inoperative MALSRL increase S-30 Cat D visibility to 1¼.</p>	<p><b>MALSRL</b>  </p>	<p><b>MISSED APPROACH:</b> Climb to 1000 then climbing left turn to 2200 direct HYP VOR/DME and hold.</p>
----------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------	-----------------------------------------------------------------------------------------------------------

ASOS <b>132.175</b>	NORCAL APP CON <b>120.95 269.45</b>	UNICOM <b>122.7 (CTAF) 0</b>
------------------------	----------------------------------------	---------------------------------



CATEGORY	A	B	C	D
S-30	540-½	384 (400-½)		540-1 384 (400-1)
CIRCLING	540-1 384 (400-1)	620-1 464 (500-1)	620-1½ 464 (500-1½)	720-2 564 (600-2)

SW-2, 16 MAR 2006 to 13 APR 2006

SW-2, 16 MAR 2006 to 13 APR 2006